


Mitigating Murphy's Law While Test




Frédéric Dollinger

Curriculum Vitae


Frédéric Dollinger

- HAEFELY HIPOTRONICS
factory Basel – Switzerland
- Area Sales & Marketing Manager
- Dipl. –Ing. / M.Sc. Mechatronic
- Language: English, German, French
- fdollinger@haefely.com






About Us





History



Our Product Range





Agenda

- Introduction to Murphy's Law
- Murphy's Law – Case Study
- Cases Study Analysis



Introduction to Murphy's Law

Anything that can go wrong will go wrong

Synopsis

- The law's author was Edward A. Murphy, Jr., a U.S. Air Force engineer, who, in 1947, was involved in a rocket-led experiment in which all 16 accelerator instruments were installed in the wrong way, resulting in Murphy's observation.

Case study

- **Origin:** this study shares what has been seen and experienced onsite from us
- **Target:** provide important insight and illuminate previously hidden issues
- **Systematic approach:** each case is studied with the mention of the fault, the cause of the fault, the consequence and the solution.





Murphy's Law – Case Study

Case Study: HV 1

Situation

Induced Voltage Test

Problem

C-Bank explosion

Factory on fire

Difficulty:
Low

Failure:
System

Cause

C-Bank was in the test circuit
during the induced voltage test

Consequence


72 kV / 200 Hz applied on
a 20 kV 60 Hz C-Bank

Can be avoided:
Yes

Dangerous:
Yes

Case Study: HV 1

- Classic test system for induced voltage test, no load and load loss, heat run
- Typical example for heat run: 20 kV / 60 Hz
- Typical example for induced voltage test: 72 kV / 200 Hz



Case Study: HV 1




- C-Bank fire is most of the time a dramatic situation, as the bank is installed inside the factory!



Case Study: HV 1

- Solution: overall test system intelligence should avoid dangerous situation!!



Case Study: HV 2

Situation

Onsite DC Hipot on submarine cable

Problem

Ultra high voltage DC generator breaks down

Difficulty:
Low

Failure:
human

Cause

Customer replaced the damping resistance, which was wrongly designed

Consequence

After cable break down, the flash went back to the DC generator, the damping resistance could not stop the high current and the DC generator breaks down

Can be avoided:
Yes

Dangerous:
Yes

Case Study: HV 2



- Onsite test on a 35 km submarine cable
- The onsite test cabin was too small
- Customer decides to replace the damping resistor with a shorter damping resistor. (same resistance value!)
- DC hipot at 380 kV
- Breakdown of the cable
- Flash back with huge current to the damping resistor, the flash goes over the resistor and destroys the generator

Case Study: HV 3

Situation

Applied voltage test

Problem

Flash

Cause

Wrong divider ratio setting

Consequence

Flash

Difficulty:
Low

Failure:
Human

Can be avoided:
Yes

Dangerous:
Yes

Case Study: HV 3



Case Study: Imp 1

Situation

Impulse test on power transformer

Problem

Overlapping oscillation

Cause

Impulse generator too far from test object, no-air cushion to move it closer to the test object

Consequence

High loop inductance
 L_{loop}

Difficulty:
Low


Failure:
System

Can be avoided:
Yes

Dangerous:
No



Case Study: Imp 1

- Relative overshoot magnitude β' shall not exceed 5% (IEC 60076-3 ed3.0)



Case Study: Imp 1

- Usual test setup for LI test
- The higher L_{loop} , the higher overlapping oscillation




Impulse Generator

Transformer

- C'_s : resulting impulse capacitance
- R'_s : Front (series) resistor
- R'_p : Tail (parallel) resistor
- L_{loop} : inductance of test circuit
- L_b : inductance of transformer
- C_b : capacitance of transformer

Case Study: Imp 1

- Solution: have an impulse generator with air cushion



Case Study: Imp 1

- Solution: have an impulse generator with air cushion



Case Study: Imp 2

Situation

LI test on power transformer, on the low voltage side

Problem

Tail time t_2 too short, out of the IEC 70076.3 ed 3.0 specification

Difficulty:
Low

Failure:
System

Cause

Very low transformer winding inductance

Consequence

Short Tail time t_2
Does not fulfill IEC 70076.3 ed 3.0

Can be avoided:
Yes

Dangerous:
No

Case Study: Imp 2


- IEC 60076-3 ed 3.0

13.2 Full wave lightning impulse test (LI)


13.2.1 Wave shape, determination of test voltage value and tolerances

The test impulse shall be a full standard lightning impulse $1,2 \pm 30 \% / 50 \mu\text{s} \pm 20 \%..$


The test voltage value shall be the test voltage value as defined in IEC 60060-1 (after the test voltage function is applied). If the maximum relative overshoot magnitude is 5 % or less, the test voltage value may be taken as the extreme value as defined in IEC 60060-1.



Case Study: Imp 2



Case Study: Imp 2



- C_b : 13nF
- L_b : 1.1mH


Case Study: Imp 2

Generator configuration	Tail time T_2 [μs]
1s2p with Rp	16.7
1s6p with Rp	17.2
1s2p with Rp and Glan- inger	45.1

- Even with more capacitance, T_2 would not rise
- Glaninger: T_2 is 270 % higher as with the 1s2p config.
- **Glaninger is the smart solution**

Case Study: Imp 2

- Solution: Glaninger Circuit



Case Study: Imp 3

Situation

Impulse voltage test

Problem:

During the impulse generator configuration:
low / medium energy discharge to the operator

Difficulty:
Low

Failure:
System

Cause

Capacitor was not grounded after use; the capacitor is charging alone back due to internal polarization phenome



Consequence

Risk of low / medium discharge to the operator, risk to fall down from the sky lift

Can be avoided:
Yes

Dangerous:
Yes

Case Study: Imp 3





Caution without grounding:
Risk of discharge!

the capacitor is charging
alones back due to internal
polarization phenome

Cap.: 1-3 μF / 100 KV

Case Study: Imp 3

Solution: Auto. grounding



Case Study: PD 1

Situation

PD measurement

Problem

Flash

Difficulty:
High

Failure:
Human

Cause

Floating coupling capacitor

Consequence

Flash between divider and
ground

Can be avoided:
Yes - no


Dangerous:
Yes

Case Study: PD 1




Case Study: PD 1

- Usual test setup: AC source + coupling capacitor + meas. Imp. + PD detector
- Test engineer has 2 PD detectors / measuring impedances (end user request)
- He changes the measuring impedance and forgets to ground it
- Coupling capacitor is floating
- Flash occurs while rising voltage
- After power off, the coupling cap. remains charged: dangerous situation



Case Study: PD 1



Case Study: PD 2

Situation

PD Measurement on
transformer

Problem:

Wrong PD values/measurement

Difficulty:
Low

Failure:
Human

Cause

Operator did not calibrate the
measuring circuit for each new
test object

Consequence


Each test object has different
capacitance, which makes
impossible to know the PD
amplitude

Can be avoided:
Yes

Dangerous:
No


Case Study: PD 2

- Calibration procedure: inject an know q_0 impulse and adjust the ratio at the detector.



Case Study: PD 2

- Calibration procedure:



Case Study: PD 3

Situation

PD Measurement on
transformer

Problem:

High PD values/measurement

Cause

Fixed dead time leading to
ambiguous recognition of partial
discharge pulse

Consequence

Partial discharge undershoot is
interpreted as pulse

Difficulty:
Medium


Failure:
System

Can be avoided:
Yes

Dangerous:
No

Case Study: PD 3


- Dynamic dead time VS fixed dead time



- Dynamic dead time: 1 pulse
- Fixed dead time: up to 3 pulses

Case Study: PD 3



- Typical situation:



- This is one partial discharge pulse
- Dead time: time to blind out the undershoot

Case Study: PD 3

- Dynamic dead time VS fixed dead time:




- Pulse polarity:
 - a) ambiguous recognition due to **fixed** dead time, wrongly set
 - b) distinct recognition without ambiguity, thanks to **dynamic** dead time (automatic)

Case Study: PD 3

- Dynamic dead time VS fixed dead time:
 - Challenge with fixed dead time settings: each PD source might need another setting!

- Inner PD source
 - Internal cavity/void in insulating material
 - Air bubbles in oil
 - Non-uniformities in SF6 insulation system
- Outer PD source:
 - Corona
 - Surface (gliding/creeping discharges)



Case Study: PD 4

Situation

PD Measurement on transformer

Problem:

Wrong PD measurement

Difficulty:
Low

Failure:
System / human

Cause

Measurement out of the IEC standard measurement band (higher frequency range)

Consequence


On the higher frequency range, the PD activity is not visible anymore

Can be avoided:
Yes

Dangerous:
No

Case Study: PD 4

- Wide-band PD instruments (chapter 4.3.4 in IEC 60270:2015)
 - $30 \text{ kHz} \leq f_1 \leq 100 \text{ kHz}$,
 - $f_2 \leq 1000 \text{ kHz}$
 - $100 \text{ kHz} \leq \Delta f \leq 900 \text{ kHz}$
 - PD pulse loses high frequency content while travelling thru transformer



Case Study: WR 1

Situation

Onsite winding resistance measurement on power transformer

Problem

At transformer reconnection, the substation switches off

Cause

The winding resistance is a DC measurement. The core remains magnetized after measurement

Consequence

- Magnetized core
- DC offset
- Inrush current
- Substation switches off

Difficulty:
Low

Failure:
System

Can be avoided:
Yes

Dangerous:
Yes

Case Study: Loss 1

Situation

Load Loss measurement on a power transformer

Problem

Higher loss readings

Cause

Wrong accuracy class of the Wattmeter

Consequence

Small power factor leads to high loss error readings

Difficulty:
Low



Failure:
System

Can be avoided:
Yes

Dangerous:
No

Case Study: Loss 1

- Phase angle error of 1min in the voltage or current will result in approx. 3 % error in loss meas. for a power factor of 0.01
- **Load loss at low power factor are very sensitive to phase angle errors**



IEEE Std C57.123-2010 [4.3]



Case Study: Loss 1

- During meas: the transformer behaves inductive
- Power factor tends to fall with rising values of rated power
 - Typical example:
 - **1'000 kVA** transformer: load loss 1 %, short circuit impedance 6 % of ref. impedance – power factor of the series impedance: **0.167**
 - **100 MVA transformer**: load loss 0.4 %, short circuit impedance 15 % of ref. impedance – power factor of the series impedance: **0.027**

$$P = U \times I \times \cos \phi$$

$$\frac{\partial P}{P} = \frac{\partial U}{U} + \frac{\partial I}{I} - \frac{\sin \phi}{\cos \phi} \times \partial \phi$$

$$-\frac{\sin \phi}{\cos \phi} = -\frac{\left(1 - \cos^2 \phi\right)^{\frac{1}{2}}}{\cos \phi} \approx -\frac{1}{\cos \phi}$$



Case Study: Loss 1

■ IEC 60076-8:1997

10.2 Traceability, quality aspects on measuring technique

Traceability of measurements means that a chain of calibrations and comparisons have been carried out, through which the validity of the individual measurement can be traced back to national and international standards of units preserved in recognized institutions of metrology. Evidence of such traceability should contain the following items.

a) Certified information about errors (amplitude errors and phase angle errors) of the components of the measuring system (transducers for voltage, current and power, voltage dividers and shunts, indicating or recording instruments, etc.)

This may comprise:

- certificates from the manufacturers of individual components;
- certification from calibrations carried out at independent precision laboratories;
- certificates of calibrations made in the plant by means of precision instrumentation and specialist staff brought there for that purpose;
- direct comparisons of the test room installation with a complete precision measuring system (overall system calibration).

Power Factor	Components Accuracy ¹		Overall System Accuracy ¹		Range
	Standard ²	Extended ³	Standard ²	Extended ³	
$\cos \varphi = 1.0$	$\pm 0.15\%$	$\pm 0.06\%$	$\pm 0.35\%$	$\pm 0.3\%$	105V/ $\sqrt{3}$ V .. 4200V/ $\sqrt{3}$ V; 0.5A .. 500A
$\cos \varphi = 0.5$	$\pm 0.5\%$	$\pm 0.12\%$	$\pm 0.7\%$	$\pm 0.3\%$	105V/ $\sqrt{3}$ V .. 4200V/ $\sqrt{3}$ V; 0.5A .. 500A
$\cos \varphi = 0.3$	$\pm 0.79\%$	$\pm 0.16\%$	$\pm 1.2\%$	$\pm 0.4\%$	105V/ $\sqrt{3}$ V .. 4200V/ $\sqrt{3}$ V; 0.5A .. 500A
$\cos \varphi = 0.1$	$\pm 2.14\%$	$\pm 0.36\%$	$\pm 3\%$	$\pm 1.2\%$	105V/ $\sqrt{3}$ V .. 4200V/ $\sqrt{3}$ V; 0.5A .. 500A
Voltmeter	Class 0.1				Ratio 3500V/ $\sqrt{3}$: 100V Range 105V/ $\sqrt{3}$..4200V/ $\sqrt{3}$ (3%..120%)
Currentmeter	Class 0.1				0.5A .. 500A

Case Study: Loss 2

Situation

No Load Loss measurement on a distribution transformer

Problem

Higher loss readings

Cause

Deviation on the excitation voltage

Consequence

Higher loss readings

Difficulty:
Low


Failure:
System

Can be avoided:
Yes

Dangerous:
No

Case Study: Loss 2

- **1% deviation on the applied voltage would increase 1% to 3 % the losses**
- **Solution: accurate voltage output** (step less adjustment, feedback loop with the measurement)



During no load loss measuring, the transformer is in the saturation working area

Case Study: Loss 3

Situation

No Load Loss measurement on
a distribution transformer

Problem

Higher loss readings

Cause

High THD on the voltage
waveshape

Consequence

Higher loss readings

Difficulty:
Low

Failure:
System

Can be avoided:
Yes

Dangerous:
No

Case Study: Loss 3

- **T.H.D.:** Total Harmonic Distortion



- IEC 60076-1:2011 [11.1.1]: Voltage: THD < 5%

- **T.H.D. cause:**

T.H.D. on the voltage waveshape comes mainly from the short circuit impedance of the test system

- **T.H.D. problem:**

Peaked waves with higher r.m.s. **can lead to higher losses**



Case Study: Loss 3

Example on a 2'500 kVA, 33 kV / 400 V transformer

■ Without THD Control

No-Load Loss Measurement 590 - C:\Data\2500kVA				
	Phase A	Phase B	Phase C	SUM/AVG
Voltage RMC	228.974 V	232.116 V	230.091 V	230.394 V
Loss	928.000 W	684.000 W	1.298 kW	2.910 kW
cos(Φ)	0.352	0.320	0.502	0.397
Current [%]	27.081 %	21.962 %	26.531 %	25.191 %
U THD	7.710 %	7.250 %	7.820 %	7.590 %
U THD	7.710 %	7.250 %	7.820 %	7.590 %
cos(Φ)	0.352	0.320	0.502	0.397
Idle Power	2.472 kvar	2.022 kvar	2.235 kvar	6.729 kvar
U THD	7.710 %	7.250 %	7.820 %	7.590 %



■ With THD Control

No-Load Loss Measurement 590 - C:\Data\2500kVA				
	Phase A	Phase B	Phase C	SUM/AVG
Voltage RMC	230.501 V	229.952 V	230.344 V	230.266 V
Loss	813.000 W	603.000 W	1.410 kW	2.826 kW
cos(Φ)	0.293	0.307	0.531	0.385
Current [%]	28.852 %	20.431 %	27.560 %	25.614 %
U THD	0.865 %	1.050 %	0.868 %	0.926 %
U THD	0.865 %	1.050 %	0.868 %	0.926 %
cos(Φ)	0.293	0.307	0.531	0.385
Idle Power	2.657 kvar	1.870 kvar	2.248 kvar	6.776 kvar
U THD	0.865 %	1.050 %	0.868 %	0.926 %

3% Difference




Case Study: Loss 3

Example on a 2'500 kVA, 33 kV / 400 V transformer


Without THD Control

No-Load Loss Measurement 590 - C:\Data\2500kVA													
	THD	1.	3.	5.	7.	9.	11.	13.	15.	17.	19.	21.	
U= 231.920 V	7.38917	100.000	1.673	4.502	5.545	0.759	0.440	0.517	0.112	0.092	0.022	0.004	
I= 8.660 A		100.000	9.815	59.815	38.568	2.771	3.926	2.887	0.462	0.577	0.577	0.231	
U= 231.400 V	6.91029	100.000	1.806	4.529	4.654	1.305	0.864	0.264	0.151	0.039	0.035	0.004	
I= 6.310 A		100.000	21.712	82.409	40.571	4.279	5.864	3.962	1.268	1.268	0.317	0.317	
U= 231.810 V	7.53547	100.000	0.242	5.781	4.620	0.828	1.169	0.483	0.039	0.112	0.035	0.009	
I= 8.120 A		100.000	13.670	71.798	36.823	4.064	4.680	2.833	1.232	1.108	0.369	0.369	



With THD Control


No-Load Loss Measurement 590 - C:\Data\2500kVA													
	THD	1.	3.	5.	7.	9.	11.	13.	15.	17.	19.	21.	
U= 231.360 V	0.09098	100.000	0.056	0.009	0.039	0.043	0.039	0.009	0.009	0.069	0.009	0.009	
I= 10.070 A		100.000	19.662	69.215	44.389	6.951	12.115	5.859	0.695	0.794	0.596	0.199	
U= 230.570 V	0.13428	100.000	0.065	0.061	0.061	0.061	0.013	0.017	0.048	0.065	0.030	0.009	
I= 6.380 A		100.000	44.201	83.542	47.022	12.539	12.696	6.270	1.097	0.784	0.470	0.313	
U= 231.240 V	0.09882	100.000	0.022	0.043	0.052	0.043	0.030	0.009	0.043	0.074	0.035	0.004	
I= 9.590 A		100.000	14.703	70.907	45.255	5.422	12.200	6.048	0.834	0.834	0.417	0.104	



Case Study: Loss 3

Example on a 2'500 kVA, 33 kV / 400 V transformer

Without THD Control



With THD Control



Case Study: Loss 4

Situation

No Load Loss measurement on
a distribution transformer

Problem

Higher loss readings

Cause

Unsymmetric voltage
waveshape

Consequence

Higher loss readings

Difficulty:
Low

Failure:
System

Can be avoided:
Yes

Dangerous:
No

Case Study: Loss 4

Example on a 2'500 kVA, 33 kV / 400 V transformer

Without Symmetry Control

No-Load Loss Measurement 590 - C:\Data\2500kVA				
	Phase A	Phase B	Phase C	SUM/AVG
Voltage RMC	232.147 V	234.035 V	230.442 V	232.208 V
Loss	1.073 kW	548.000 W	1.290 kW	2.909 kW
cos(Φ)	0.328	0.211	0.482	0.343
Current [%]	33.852 %	26.483 %	27.967 %	29.434 %
U THD	2.450 %	2.170 %	2.760 %	2.460 %
U THD	2.450 %	2.170 %	2.760 %	2.460 %
cos(Φ)	0.328	0.211	0.482	0.343
Idle Power	3.087 kvar	2.530 kvar	2.347 kvar	7.963 kvar
U THD	2.450 %	2.170 %	2.760 %	2.460 %



With Symmetry Control

No-Load Loss Measurement 590 - C:\Data\2500kVA				
	Phase A	Phase B	Phase C	SUM/AVG
Voltage RMC	230.501 V	229.952 V	230.344 V	230.266 V
Loss	813.000 W	603.000 W	1.410 kW	2.826 kW
cos(Φ)	0.293	0.307	0.531	0.385
Current [%]	28.852 %	20.431 %	27.560 %	25.614 %
U THD	0.865 %	1.050 %	0.868 %	0.926 %
U THD	0.865 %	1.050 %	0.868 %	0.926 %
cos(Φ)	0.293	0.307	0.531	0.385
Idle Power	2.657 kvar	1.870 kvar	2.248 kvar	6.776 kvar
U THD	0.865 %	1.050 %	0.868 %	0.926 %



3% Difference

Case Study: Loss 5

Situation

No Load Loss measurement on a transformer

Problem

Higher loss readings

Cause

Magnetized core

Consequence

Higher loss readings

Difficulty:
Low

Failure:
Human

Can be avoided:
Yes

Dangerous:
No



Case Study: Loss 5

- Prehistory of magnetization
 - Remanence in the core after saturation during winding resistance meas. or by unidirectional long-duration impulses, may leave a trace in the no load loss meas.
 - A systematic demagnetization of the core before no load meas. is recommended to establish representative results

IEEE Std C57.123-2010 [3.2.2]

60076-8 IEC:1997 [9.6]

Case Study: Loss 5

- ABB Book: ABB_2010_Testing of Power Transformers and Shunt Reactors, Routine Type and Special Tests, page 72 - the No-Load loss:

Before the loss measurements actually take place the transformer to be tested must be excited by 1,1 to 1,15 times rated voltage. The over-excitation reduces the effects of remanence caused by DC current excitation during resistance measurements or from the switching impulse. The correct no-load loss cannot be seen until there have been several cycles of the magnetizing characteristic. During this process the readings of the ammeters and wattmeter decrease. When the measured figures are steady, the actual loss measurements can start.

Case Study: FRA

Situation

FRA Measurement on power transformer

Problem:

Measurement differs from reference

Difficulty:
Medium - High

Failure:
human

Cause

Multiple: Oil, magnetization, connection, temperature

Consequence

FRA shows deviation

Can be avoided:
Yes

Dangerous:
No

Case Study: FRA

- Power Transformer filled with different oil onsite as at the factory




Figure B.12 – Effect of different types of insulating fluid on frequency response

Ref: IEC 60076-18 ed 1.0

Case Study: FRA

- Power transformer measured onsite before filling the oil




Figure B.13 – Effect of oil filling on frequency response

Ref: IEC 60076-18 ed 1.0

Case Study: FRA

- Power transformer measured after winding resistance measurement without demagnetization




Figure B.14 – Effect of a DC injection test on the frequency response

Ref: IEC 60076-18 ed 1.0

Case Study: FRA

- Power transformer measured at different temperature




Figure B.16 – Effect of temperature on frequency response

Ref: IEC 60076-18 ed 1.0

Case Study: FRA

- Power transformer measured with bad connection





Figure B.17 – Examples of bad measurement practice

Ref: IEC 60076-18 ed 1.0


Case Study: FRA

At the highest frequencies of above 1 MHz ($> 72,5$ kV) or above 2 MHz ($\leq 72,5$ kV), the response is less repeatable and is influenced by the measurement set-up, especially by the earthing connections, which effectively relies on the length of the bushing.



Influence regions:

- A core
- B interaction between windings
- C winding structure
- D measurement setup and lead (including earthing connection)



- A connection clamp
- B unshielded length to be made as short as possible
- C measurement cable shield
- D central conductor
- E shortest braid
- F bushing
- G earth connection
- H earth clamp
- I tank
- J smallest loop

Case Study: PF 1

Situation

Power factor measurement on transformer

Problem:

Wrong measurement

Difficulty:
Low

Failure:
human

Cause

Dirty bushing

Consequence

Leakage current increases the power factor

Can be avoided:
Yes

Dangerous:
No

Case Study: PF 1



Case Study: PF 2

Situation

Power factor measurement on transformer

Problem:

Wrong measurement

Difficulty:
Low

Failure:
human

Cause

High humidity during the measurement (morning, after rain, snow, etc...)

Consequence

Leakage current increases the power factor

Can be avoided:
Yes

Dangerous:
No



Case Study: PF 2

- Rules of dump
 - 65 % rel. humidity: 10 x higher leakage current
 - 80 % rel. humidity: 100 x higher leakage current
 - 95% rel. humidity: 1000 x higher leakage current

- Depending on the test object, leakage current can have a large impact. We do not recommend to measure above 65 % - 80 % rel. humidity

Case Study: PF 3

Situation

Power factor measurement on transformer

Problem:

Wrong measurement

Difficulty:
Low

Failure:
human

Cause

Wrong temperature correction

Consequence


Temperature correction depends on the test object. A wrong setup gives high deviation

Can be avoided:
Yes

Dangerous:
No

Case Study: PF 3

■ Temperature correction example



Case Study: PF 4

Situation

Power factor measurement on transformer

Problem:

Impossible to perform correct measurement

Difficulty:
Low

Failure:
System

Cause

GST setup is needed, but the power supply is not compatible

Consequence


If the power supply does not have a separate ground output, is it impossible to perform a GST measurement.

Can be avoided:
Yes


Dangerous:
No

Case Study: PF 4

- UST and GST test setup:



Ungrounded specimen test **UST**



Grounded specimen test **GST**

Cases Study Analysis



Anything that can go wrong will go wrong,

But all situations could have been avoided!!!!!!!





Technology level

- If a system is the cause of a fault, upgrading the system would be the solution

Better technology will avoid system failure!



Safety

- Half of the dangerous situations are caused by the system technology. Upgrading the system would fix the problem.

Think safety first and if requested upgrade the system!



Knowledge

- Half of the problems are linked to operator knowledge. Read the user manual first and get trained!





감사합니다 Natick
Danke Ευχαριστίες Dalu
Thank You Köszönöm
Grazie Tack
Спасибо Dank Gracias
谢谢 **Merci** Seé
ありがとう